Joseph P. Teasdale Governor



Carolyn Ashford Director

missouri department of natural resources

1155 E Cherokee St

Springfield Regional Office Springfield, Missouri 65807

417-883-4033

August 18, 1977

Mr. John Matthews 2710 North Fulbright Springfield, MO 65803

Dear Sir:

Please find enclosed a copy of the report on analysis for the sample collected on July 28, 1977 from the waste treatment facilities serving the Lakewood Mobile Home Park.

You will note that the sample results indicate that the discharge exceeds the interim limitations by a considerable amount. For this reason, Ed Sears and I plan to inspect the facilities in an attempt to determine the problem. We will contact you prior to our visit.

If you have any questions, please advise.

Yours truly,

Charles L. Kroegér

Environmental Specialist II Springfield Regional Office

Department of Natural Resources

CLK/jo

Enclosure

cc Water Quality Program
Mr. Bob Corson, City of Springfield

mme. 2710 N. FULBRIGHT

JOSEPH P. TEASDALE GOVERNOR



CAROLYN ASHFORD DIRECTOR

missouri department of natural resources

2010 Missouri Blvd.

P.O. Box 1368

Jefferson City, Missouri 65101

314-751-3241

LABORATORY SERVICES PROGRAM

REPORT OF SAMPLE ANALYSIS

August 10, 1977

Sample Description Lab	cewood Mobile Home Pa	ark	No.	77-8031
Collected By <u>C. Kroeg</u> e	er	Region SRO	Date	7-28-77
Remarks				
g g				
HELL PLANES AND THE SECOND				
PARAMETER	mg/1	PARAMETER		<u>UNITS</u>
BOD COD	156	pH *Temperature °C		
Suspended Solids (NFS)	95			
Ammonia as N Nitrate + Nitrite-N Total Nitrogen (TKN)		Specific Conductance umhos @ 25 °C	e	
Orthophosphate as P Total Phosphorus Alkalinity		Fecal Coliform Bacteria per/100 m	mls. ª	

The analysis of this sample was performed in accordance with procedures as outlined in the latest edition of Standard Methods for the Examination of Water and Wastewater, EPA manual of Methods for Chemical Analysis of Water and Wastes, and/or Annual Book of ASTM Standards.

James H. Long

Director

Laboratory Services

JHL:mh

*Analysis performed by collector.

Division of Environmental Quality

2710 N. FULBRIGHT